


PP-10A Mini Combo Pen Heat Press





ASSEMBLY DRAWING












TECHNICAL PARAMETERS



NO.	Part Name	Qty
1	Machine Frame Welding Diagram	1
2	Left Lateral Plate Handle	1
3	Handle Sleve	2
4	Limit spacer	1
5	Mirrored Left Lateral Plate of Davit Arm	1
6	Handle	1
7	Handle Spindle	1
8	Left and Right Lateral Plate of Davit Arm	1
9	Davit Arm Limit Board	1
10	Mirrored Left and Right Lateral Plate of Davit Arm	2
11	Fixing Bolt of Handle	2
12	Fixing Bolt of Davit Arm	1
13	Gas Spring Tube	1
14	Gas Spring Connector	1
15	Gas Spring	1
16	Electric Box	1
17	prat0155SHY	1
18	Case of Digital Controller	1
19	Panel of Digital Controller	1
20	Solid-state Relay	1
21	Transformer	1

NO.	Part Name	Qty
22	Suffix Power Cord	1
23	Small Four-core Aviation Plug	1
24	Heat Platen Connecting Board	1
25	Heat Platen Cover	1
26	Pen Tray Silicon Pad	2
27	Cap Heater Connecting Board	1
28	Under Platen	1
29	Adjusting Screw	1
30	Positioning Welding Shaft	1
31	Locating Sleeve of Adjusting Screw	1
32	Hat Jackstar	1
33	Hand Wheel	1
34	Machine Feet	1
35	Conic Machine Feet	1
36	Connectin Board	2
37	Connectin Board Distance POM	2
38	Distance Sleeve of Connecting Board	2
39	Fixing Bolt of Connecting Board	1
40	Gas Spring POM Bar	2
41	Gas Spring Shaft	1

III.Mainenance

- 1. In order to prolong the machine service life, please add the lubrication oil on the joints regularly.
- 2. Turn off the power before changing spare parts. In order to ensure the accuracy of the parameter of GY-10 controller, please re-set the time and temperature.
- 3. To avoid damage, please keep the heaters well when cjihange the spare parts.

III. Trouble shooting for transfer print quality

1. After changing mug heater, time and temperature showing become abnormal:

Solution: Reset time/temperature according the manual

2. If the color is not as bright as photo after printing, please try below ways:

Solution: A. Adding transfer time. B. Increasing transfer temperature.

3. If the print color is too brown or the transfer paper is almost burnt:

Solution: Please reduce the setting temperature.

4. If print color is different/ partial transfer effect is not good enough:

Solution: A. Increase the pressure. B. Extend the transfer time. C. Change the sublimation paper

5. If the machine is getting abnormal, please contact us to solve the problems.

V. CIRCUIT DIAGRAM

